

**Subdivision – Land O’ Lakes Florida**  
**Contractor should have used Tuf-Link!**



Expensive Repair



Delamination from water penetration



Hydration Cracking



Water Penetration